"What's Wrong With This Picture"

Presented by: Debbie Hurst RN, CIC, FAPIC


North Dakota Infection Prevention and Control Conference



Instructions





What's wrong? Left side is department office entrance, right side is soiled linen holding overflow area.






What is of the Infection Control Concern in the EVS Closet?





Why is visible dust on this vent a problem for infection control?





Your thoughts?



Your thoughts?



Public restroom in hospital, throughout the facility




Floor drain in restroom




In surgery staff break room corner



Mops organized by type and purpose: is this a best practice?




Another best practice for microfiber mop program?




Sink in the med room...



Med room sink from before (> visibility of the left side of sink use)



Sink in clean supply room



THANK YOU!